

KX155 Nav Com



This KX155 was removed from N5LL PA31 during avionics refit in 2008 (EASA Form 1 issued following repair and serviceability check).

List price new today is \$4375 for the KX155 (FM immune)

King KX155 (28volts only without Mod16 FM immunity) Tray not included.

P/N 069-1024-43

S/N 100574

Sale price £1250